

INSTALLATION INSTRUCTIONS FOR UA PRODUCTS :UA0767 F Caldwell

INSTRUCTIONS:

1. Unscrew bracket bar cap and remove bracket bar with threaded stem and safety cable attached.
2. Mount bracket bar to junction box.
3. Attach safety cable to fixture using screw provided on top edge of fixture.
4. Connect white wire to white supply wire.
5. Connect black wire to black supply wire.
6. Connect ground to junction box.
7. Slide fixture over threaded stem and tighten bracket bar cap.

WARNING:

**RISK OF FIRE AND ELECTRICAL SHOCK IF IMPROPERLY INSTALLED.
MUST BE INSTALLED BY A LICENSED ELECTRICIAN ACCORDING TO
INSTRUCTIONS PROVIDED.**

CAUTION:

TURN OFF POWER AT MAIN ELECTRICAL BOX BEFORE INSTALLATION.

Type O
